



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

0001

**Inspection Report**  
**Minerals Regulatory Program**  
January 4, 2010

Reviewed: 

<b>Mine Name:</b> Sevier Mining Claim #1-8	<b>Permit Number:</b> S/041/0038
<b>Operator Name:</b> Knotts & Co.	<b>Inspection Date:</b> June 2, 2009
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 8:00 am
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Purpose of Inspection:**

Routine Inspection while in the area.

**Inspection Summary:**

This operation was approved May 2, 2008. A reclamation surety (CD) for \$10,000 has been provided for the 1 acre of proposed disturbance. There has been some activity at the site. Areas disturbed were regraded and seeded. Vegetation was beginning to germinate. There were no signs of excessive erosion. Subsequent contact with the operator indicated that he was planning to do more work at the site. As per the agreement he had with Water Rights, disturbances are to be reclaimed each year. This is being done.

Photos were taken to document site conditions.

**Conclusions and Recommendations:**

This site is apparently in compliance at this time. Continue to monitor this site when in the area.

**Inspector's Signature** \_\_\_\_\_

cc: Terry Krasko, Forest Service

O:\M041-Sevier\S0410038-SevierMiningClaim108\inspections\Insp-06022009.doc

0001